



CRS - Color Variant (WHITE)
1500 Hours ASTM B117 Salt Spray

Left: Scribed panel shows bubbling and rust development in and around immediate area of scribe (V shape). No rust migration under coating, no peeling, coating stays in tact.

Right: Non-scribed panel. No signs of failure. Taped edges allowed some rust from uncoated edges to bleed through the tape. Coating shows no signs of failure.